Version: UPS 03.5
Applicable SKUs:
===============
ID 1015 and 1018, All standard SKUs beginning with SMT and SMC prefixes.
SMT: SMT750C, SMT750RM2UC, SMT1000C, SMT1000RM2UC, SMT1500C, SMT1500RM2UC, SMT2200C, SMT2200RM2UC, STM3000C, SMT3000RM2UC
SMC: SMC1000C, SMC1000RM2UC, SMC1500C, SMC1500RM2UC, SMC1000IC, SMC1000I-2UC, SMC1500I, SMC1500I-2UC

Change logs:
1.   Implement DOE function to improve power efficiency.
2.   Improved SmartConnect cloud connectivity and ability to reconnect to the cloud over time.
3.   Reporting UPS events (for example: battery disconnected, output on, etc.) more accurately to SmartConnect cloud server.

Previous Released Version: UPS 03.2
Applicable SKUs:
===============
ID 1015 and 1018, All standard skus beginning with SMT and SMC prefixes.
SMT: SMT750C, SMT750RM2UC, SMT1000C, SMT1000RM2UC, SMT1500C, SMT1500RM2UC, SMT2200C, SMT2200RM2UC, STM3000C, SMT3000RM2UC
SMC: SMC1000C, SMC1000RM2UC, SMC1500C, SMC1500RM2UC

Change logs:
1.   Enable boost charger function.
2.   Improve the battery over-temperature-protection function. The UPS will pop-up message on LCD for user to recognize.
3.   Added an OEM feature - auto turn on when AC is within range.
4.   Allow configuration and acknowledgement of Site Wiring Fault.
5.   Added an event reporting to could when Outlet status changes.
6.   Fixed reversed setting in Modbus configuration.
7.   Improved a status reporting to cloud related with pending off for UPS.
8.   LCD Display of runtime remaining when runtime less than one minute will report "< 1m"
9.   Change default choice for confirming installation of firmware now (output on) to CONFIRMED, not CANCEL.

Initial Released Version: UPS 02.6
Applicable SKUs:
===============
SMT: SMT750C, SMT750RM2UC

Compatibility:
=============
AP9613 Dry Contact Version Next Gen Relay IO card 2.1
AP9620 LCC Version 3.0
AP9624 (Second Gen Interface Expander Card) v1.0X
AP9631/AP9630 card APP SUMX 6.2.1, AOS 6.2.1
AP9635 CH / AP9631card APP SUMX 6.4.6, AOS 6.4.6